


NOTE: ALL TIE POINTS MARKED  
① WERE REPLACED WITH LEAD  
& TACK AT SAME LOCATION AFTER  
SIDEWALK RE-CONSTRUCTION IN MAY 2000  
AND NOV. 2003.



REVISED

5-16-00  
11-2003

§ 11-2003

FALCONIER  
HUEFETA

HUEICTA