

TIES CHECKED
Apr. 16, '73
J. Chesney

110

Pg. 1 of 3


FB19 25

REVISED 2/2001
SEALE
FALCONIERI
HUERTA

(CONT. FROM P. 24)

CROSS SECTION

2-689.16



6-21-00

(A), (B) - FOUND DRIVE PINS AND TIED THEM OUT PRE-CONSTRUCTION AND PUT THEM BACK IN THE SAME LOCATION AFTER CONSTRUCTION WITH LEAD & TACK.

(C) - FOUND SET IN PP412559. POLE IS LEANING WEST 3FT ± AT THE TOP WHICH MAY ACCOUNT FOR THE DISTANCE TO INTERSECTING (A) AND (B) 0.15 ± LONG.

6-21-00

(A) - FOUND 2 DRIVE PINS 1.32FT APART, BOTH AT 40.20 TO THE RECORDED DISTANCE OF 40.21 FROM (B). ONE OF THE (A) PINS "MAY" BE A P.I. PROPERTY LINE PROD. FOR DONALOR DR. AND BOYLE AVE. ROY KLEMA, RCE 6486, OFTEN SET SUCH P.I. PINS IN CONC. CURB OR GUTTER OR SIDEWALK AND NOT CALL THEM OUT ON HIS SUBDIVISION MAPS. M-7201 FOR DONALOR DR. SHOWS NO SUCH CORNER SET. NO EFFORT WAS MADE TO VERIFY ONE OF THE (A) PINS AS SUCH.