


- △ = Find Spike & Tin LS 5292
 ○ = Set Ld & TK in T.C. or as noted
 □ = Find Ld & DISC LS 5292




- 21.99
 1 22.05
 2 21.56
 3 20.61
 4 20.34
 5 22.71
 6 21.17
 7 20.72
 8 23.42

Not to Scale


- 9 20.20
 10 19.24
 11 18.94
 12 20.23
 13 24.09
 14 21.79
 15 18.81
 16 21.81
 17 34.65
 18 30.43
 19 30.85
 20 35.55

Not to Scale



Silver Oak Place

Put in D.W.



Lot 22

Way