

# **Notice of Completion:**

## **2018 Street Maintenance Project**

August 21, 2019



# PAVEMENT MANAGEMENT PROGRAM:

Focus on 1 of 8 Residential/Maintenance Zones & Select Major Streets

## MAJOR ELEMENTS

Street Treatment

Sidewalk Repairs

Pedestrian Ramps

Vehicle Detection Cameras

Street Trees

Update Striping

Bike Lanes




— 2015  
58 lane miles

— 2016  
67 lane miles

— 2017  
94 lane miles

--- 2018  
98 lane miles





# STREET TREATMENTS — 17<sup>TH</sup> AVENUE

Before



After





# STREET TREATMENTS — CITRACADO PKWY

Before



After





# STREET TREATMENTS —HAMILTON

Before



After





# STREET TREATMENTS – SUNSET

Before



After





# STREET TREATMENTS —TAMARME TERR

Before



After





# SIDEWALK REPAIRS / PEDESTRIAN RAMPS

Before



After





# SIDEWALK REPAIRS / PEDESTRIAN RAMPS

Before



After





# OTHER PROJECT ELEMENTS —CROSS GUTTER INSTALLATION AT BERKSHIRE COURT

Before



After



# OTHER PROJECT ELEMENTS—CROSS GUTTER AT MILLER/BROTHERTON

Before



After





# VEHICLE DETECTION CAMERAS



# TREE REMOVAL/REPLACEMENT

Before



After





# TREE REMOVAL / REPLACEMENT

Before



After



# TREE REMOVAL / REPLACEMENT

Before



After





# VERMONT AVENUE



# FELICITA ROAD





# CITRACADO / CENTRE CITY PARKWAY



# ESCONDIDO BLVD





# BEAR VALLEY PARKWAY




# BEAR VALLEY PARKWAY






# What's Next?

## --- 2019



# Pavement Deterioration Curve

(Best strategy at the appropriate time)





# CITY-WIDE STREET EVALUATION

Laser Road Surface Testing  
Van



Road Surface Testing  
Lasers



# **RECOMMENDATION — ADOPT RESOLUTION 2019-129, ACCEPTING THE 2018 STREET MAINTENANCE PROJECT AS COMPLETE**

